CIVIL-TECH CONSULTANTS AND ENGINEERS

Building & Highway Material Testing Laboratory

An ISO 9001:2008 Certified Company

NABL - Accredited Laboratory as per ISO / IEC-17025 : 2005

JAS-ANZ BSCIC ISO 9001 REGISTERED

Job No.: CTCE/BBMP/Consultants/313/2017-18

Dated: 29.03.2018

To,
Executive Engineer,
Dasarahalli Division,
BBMP, Bangalore.

Sir,

Sub: Consultancy Services for the work of Improvements to drain at Munikondappa layout at Bagalagunte in Ward No.14 BBMP, Bangalore.

Ref:
1. Work Order No.: EE/DD/WO/206/2017-18 Dated: 23.01.2018
2. Job Code: 014-18-000018

We are herewith forwarding to Mr. J.C Ramchandra, First and Final bill duly verified and certified that the work is satisfactory and for a Gross Value of Rs. 50,07,358.00/- (Rs. Fifty lakhs Seven Thousand Three Hundred and Fifty Eight Only) for further needful.

Thanking you,

Civil-Tech Consultants & Engineers Bangalore

Yours faithfully,
For Civil-Tech Consultants and Engineers

Technical Manger

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರ
ಟಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ. ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

#23/14, 7th Cross, 3rd Stage, 4th Block, Shakthi Ganapathi Nagara, Basaveshwaranagar, Bangalore-79.
Tele Fax : 23223227, Website : www.civiltechconsultants.com
E-mail : vishwanath.ia@civiltechconsultants.com / info@civiltechconsultants.com

Scanned by CamScanner

Photograph was taken at the time of Inspection (26.03.2018) Improvements to drain at Munikondappa layout at Bagalagunte in Ward No.14 BBMP, Bangalore.



Civil-Tech Consultants & Engineers Bangalore

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರ
ಟಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

Scanned by CamScanner

Improvements to Drain at Municipal office Layout at Bagalgunte In Ward-14

Scanned by CamScanner

Improvements to Drain at Ramakondapalli Layout at Bagalgunte in Ward No:-14.

Scanned by CamScanner

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರ
ಟಿ.ದಾನರಡ್ಡಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬೆಂಗಳೂರು

Scanned by CamScanner

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರು
ಟಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

Scanned by CamScanner